

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
MONT.
32-MILTO,
1-B-

Milltown Dam, Spillway
On the Clark Fork River
Town of Milltown
Missoula County
Montana

HAER No. MT-43-B

Paul Anderson, Photographer, May 1988

MT-43-B-1	DAM SPILLWAY, TO SOUTH
MT-43-B-2	DAM SLUICE GATES, TO SOUTH
MT-43-B-3	DETAIL OF DAM LIFT MOTORS FOR SLUICE GATES
MT-43-B-4	PENSTOCK GATES ALONG FOREBAY WALL, VIEW TO NORTH
MT-43-B-5	DETAIL OF PENSTOCK GATES, VIEW TO NORTHEAST

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

ADDENDUM TO:

HAER MT-43-B

MILLTOWN DAM, SPILLWAY

Clark Fork River, 6 miles upstream from Missoula

Milltown

Missoula County

Montana

Photographs HAER MT-43-B-1 through HAER MT-43-B-5 were previously transmitted to Library of Congress.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Kristi Hager, photographer, March 2007

MT-43-B-6	Top of Spillway, view to north
MT-43-B-7	New overflow gate from top of Spillway, view to north
MT-43-B-8	Overflow gate from up river, view to west
MT-43-B-9	Overflow gate looking down river, view to northeast

INDEX TO COLOR TRANSPARENCIES

Kristi Hager, photographer, March 2007

MT-43-B-10 (CT)	Overflow gate from up river, view to west
MT-43-B-11 (CT)	Spillway, view to southwest